



1965 Jaguar Mk2 3.8 MOD

The Job

This car received considerable mechanical work by us before a complete body restoration in 2014. The Mk2 has complex bodywork and requires considerable work to ensure replacement panels, particularly doors, line up correctly.

The Challenge

The car had considerable rot to the front floors, offside A pillar area, sills, doors, front wings and boot and boot floor. We stripped out all the rot, welded in new panels and effected repairs, sourced & fitted new door skins and prepared the car for paint. The sides and boot of the car were resprayed.

The Result

This Mk2 is now solid again and the work has been completed to a high standard with good panel fit. It is ready to return to our fleet for its demanding hire life. The cost of the work including paintwork was £10,000+VAT.